Column1	Column2	C2	C1	C0
T4	Op5	1	0	0
T4	Op6	1	1	0
T4	Op7	1	0	1
T4	Op8	0	0	0
T4	Op9	0	0	1
Т3	Op10	0	1	1
T4	Op11	0	1	0

Column1	Column2	Stc	Clc	Stz	Clz
Т3	OP12.IR 0	1	0	0	0
Т3	OP12.IR 1	0	1	0	0
Т3	OP12.IR 2	0	0	1	0
Т3	OP12.IR 3	0	0	0	1