Facility MRN(s): 082-40-14; 048-80-83; 070-93-28

Patient Name: LOW, Donald William

8a Buller St

SOUTH TURRAMURRA, NSW 2074

Ph: (02) 9449-3767

DOB: 26/11/1944 **Age**: 80 years **Sex**: Male



Generated by NSLHD / CCLHD Not original source document. Do not download, print or distribute.

DOCUMENT NAME: SERVICE DATE/TIME: RESULT STATUS: PERFORM INFORMATION: SIGN INFORMATION: Provisional ICD Report - Cardiology 12/05/2025 12:42 Auth (Verified) Yat,David (Technologist) (12/05/2025 12:52) Yat,David (Technologist) (12/05/2025 12:52)

Provisional ICD Report - Cardiology Dept RNSH

Patient: LOW, Mr Donald William MRN: 070-93-28

Age: 80 years Sex: Male DOB: 26/11/1944

Associated Diagnoses: **None** Author: **Yat, David (Technologist)**

Findings

Performed by

David Yat (Technologist); Medical Technician V5

CRTD check Cardiorenal; Routine

Boston SCi Resonate X4 CRT-D Implanted 16/01/2024 by Dr John Bereton @ NSP Battery 8.5 years VVIR 80-130

Sensing / Threshold / Impedance RV 10.3mV / 1.6V@0.4ms / 373 ohms LV >25mV / 1.0V@0.4ms / 809 ohms (LVa) 647 ohms (LVb) Shock 49 ohms

2x NSVT - longest lasting 20 seconds, Nil EGM

AP:0% RV 97% LV 97% CRT 100%

*** RV lead impedance very slowly trending downwards (lower ohms) & thresholds trending upwards (higher threshold) ?Possible RV lead insulation breach / leak - for monitoring ***

Otherwise device function normal, optimal CRT pacing

Checked by DY

Printed on: 12/05/2025 12:52 Page 1 of

SENSITIVE: HEALTH INFORMATION. This document has been classified according to the NSW Government Digital Information Security Policy version 2 & NSW Government Information Classification, Labelling and handling Guideline 2015. Any use of this document must comply with the policy and guidelines. This document is confidential and may contain legally privileged information. The copying of this document or any information it contains is prohibited.