
Optimal (s, S) Policies for Different Intensities of the Breaking Process (p=0.9) 40 35 30



Average Number of Parts Breaking Per Week ( $\lambda$ )