

Dhaka Power Distribution Company Ltd.

Technical Audit Division

SITE INSPECTION REPORT

Report No: **SIR-2026-DPDC-MP10-00789**

Inspection Date: **6 July 2026**

Location: **Mirpur 10, Road 5, Section 12,
Dhaka 1216**

Inspector: **Nusrat Jahan, Sub-Engineer**

Division: **DPDC Technical Audit Division**

Purpose: **Post-repair quality inspection of
electrical pole replacement**

INSPECTION FINDINGS:

- Pole Replacement:** Old pole removed and new 12m pre-stressed concrete pole erected at same position. Foundation depth confirmed at 1.8m with proper concrete base. Pole is vertical within 0.5 degrees tolerance.
- Overhead Lines:** All lines re-connected with proper tension. No sagging observed. Clearance from ground meets minimum 5.8m requirement.
- Earthing System:** Resistance measured at 3.2 ohms (within acceptable range of <5 ohms). Copper rod properly driven and connected.
- Safety Measures:** Warning signage installed. Reflective markers present. Area cordoned during work.
- Documentation:** Contractor work log reviewed. Material test certificates for pole and cables verified.

CONCLUSION:

The replacement work meets DPDC technical standards and safety requirements. All inspected items are within acceptable tolerances. Recommended for energization and public use.

Nusrat Jahan

Sub-Engineer
DPDC Technical Audit Division

[DPDC Technical Audit Division Official Stamp]