

Committee Issues Report



Generated: 11 Sept 2026, 11:15 am — By: ta.deskops@gmail.com — Pending Approval: 7 • Active: 131 — Filters: Pending=PENDING_APPROVAL


PENDING APPROVAL (7)


Ticket ID	Submitted	Tower / Unit	Resident	Category	Severity	Status	Description	Photos
TKT-00143	09 Aug 26	Tower A / A701	Gulzarsingh virdi	Civil	—	PENDING_APPROVAL	Parking stack number 35 is not operational, lift is not going up	
TKT-00142	02 Aug 26	Tower A / A701	Gulzarsingh Virdi	Miscellaneous	—	PENDING_APPROVAL	Parking number 35, stack is making a lot of grinding sound and slowing down while taking stack down	
TKT-00141	27 Jul 26	Tower A / A-701	Gulzarsingh Virdi	Plumbing	—	PENDING_APPROVAL	Complete drain blockage in dry balcony.	
TKT-00140	25 Jul 26	Tower A / A 903	Mrs. Anuradha Phatarphod	Electrical	—	PENDING_APPROVAL	The Address	
TKT-00139	25 Jul 26	Tower A / A1004	Kushal Banerjee	Security	—	PENDING_APPROVAL	CCTV to be installed at parking	
TKT-00138	25 Jul 26	Tower C / C-204	Vandana Amin Thakker	Common Area	—	PENDING_APPROVAL	The duct area is covered with horizontal strips to cover up drainage pipes etc. This is NOT part of original floor plan and it blocks sunlight and ventilation in kitchen. Pl consider removing it and replacing it by pigeon net or so. Light and ventilation is preferred over anesthetics.	
TKT-00137	22 Jul 26	Tower B / B-1204	Rohan Palande	Common Area	—	PENDING_APPROVAL	Water entering the lift lobby during rain.	



ACTIVE (131)

Ticket ID	Submitted	Tower / Unit	Resident	Category	Severity	Status	Description	Photos
TKT-00136	18 Jul 26	Tower B / B-1205	Ahmed Kanber	Plumbing	Critical	ASSIGNED	Overhead Water tanks are left open or lids are not properly closed or secured	  
TKT-00081	29 Jun 26	Common Area / A-201	Manasadevi PT	Civil	Critical	ASSIGNED	Roof is leaking above parking lot number 45 in LG	 
TKT-00078	18 Jun 26	Tower A / A1101	Prakash Yelwande	Civil	Critical	ASSIGNED	A wing entrance from road side is fully leaking and is visible during rains, kindly check and correct the leakage in cracks	
TKT-00098	13 Jun 26	Common Area	Assessment 13th June	General	Critical	ASSIGNED	Air duct placement B problem. AIR blowers at each tower are not properly placed. This is important as at time of storms it could be hazardous. This must be checked and fixed in all towers.	  
TKT-00097	13 Jun 26	Common Area	Assessment 13th June	Plumbing	Critical	ASSIGNED	Water flow points in all terraces must be properly given with mesh and prevent high pressure on pipes to avoid damages. Need to check in all terraces.	  
TKT-00096	13 Jun 26	B	Assessment 13th June	Plumbing	Critical	ASSIGNED	Water levelling B wing above 3 series. In general water clots need to be addressed in all terraces of all towers.	
TKT-00092	13 Jun 26	Common Area	Assessment 13th June	Civil	Critical	ASSIGNED	Steel Railing required at pool area above glass partition to safeguard.	
TKT-00091	13 Jun 26	A	Assessment 13th June	Civil	Critical	ASSIGNED	Gate is required at A Wing. 1st floor access to pool area as during rains it may spill over water and cause damage to LIFTS. It must be done.	 
TKT-00090	13 Jun 26	Common Area	Assessment 13th June	Electrical	Critical	ASSIGNED	Transofmr room not all machines are functional. Wires kept open on the floor. The door must be locked and key should be with the security at main door.	
TKT-00084	13 Jun 26	Common Area	Assessment 13th June	Civil	Critical	ASSIGNED	Gym Area – Cracks on the wall, plaster/paint/electric supply, flooring. It requires flooring work, electrical, fans and air conditioning (if planned within scope of builder)	

Ticket ID	Submitted	Tower / Unit	Resident	Category	Severity	Status	Description	Photos
TKT-00076	13 Jun 26	Common Area	2026-06-06T07:00:00.000Z	Plumbing	Critical	ASSIGNED	Non-Return Valve (NRV) on the balancing-tank line has not been provided. Install it. Its near filteretion tank	
TKT-00074	11 Jun 26	Common Area	Assessment 6th June	Plumbing	Critical	ASSIGNED	The overflow-tank exit pipe is missing. Route the new pipe clear of the filter and motor so that any leakage cannot fall onto the equipment.	 
TKT-00071	11 Jun 26	Common Area	Assessment 6th June	Amenities	Critical	ASSIGNED	(Glass near swimming pool) Weak support for the glass, which can break and cause injury to residents. Provide sturdy support such as steel rods, as done in the flat balconies.	 
TKT-00062	08 Jun 26	Common Area / B-201	Raj Thakker	Miscellaneous	Critical	ASSIGNED	Cleaning of duct areas and drainage before rains to avoid choked drainage	    
TKT-00051	08 Jun 26	Common Area	Assessment 6th June	Plumbing	Critical	ASSIGNED	"Carry out cleaning of the following before handover (mandatory): • Society water tank • Balancing tank • Swimming-pool tank"	
TKT-00050	08 Jun 26	Common Area	Assessment 6th June	Civil	Critical	ASSIGNED	"External-wall painting to be done last, after all civil works are complete. • Covers all floor walls, refuge areas, and any patch-work. • All ducts must be left paan / stain-free."	
TKT-00049	08 Jun 26	Common Area	Assessment 6th June	Common Area	Critical	ASSIGNED	"Strengthen the access / passage between the (A !" B !" C) wing ducts. A stur required in order to establish a fortnightly cleaning schedule for the first-floor ducts between A–B, B–B and B–C, to maintain hygiene and health. • Cleaning to be carried out under supervision only. • Builder must get this cleaned before hand-over."	
TKT-00030	07 Jun 26	Common Area	Assessment 6 June	Civil	Critical	ASSIGNED	Clear all choked drainage lines across the premises (e.g. near the duct between B-Wing and the gallery). Drainage – De-choking	
TKT-00121	06 Jun 26		Assessment 6th June	Amenities	Critical	ASSIGNED	Extend the façade up to the shade for privacy during entry / exit to the pool — shade is incomplete.	



Ticket ID	Submitted	Tower / Unit	Resident	Category	Severity	Status	Description	Photos
							Facade work needs to be completed.	
TKT-00115	06 Jun 26		Assessment 6th June	Electrical	Critical	ASSIGNED	Wires are running through standing water. Re-route them through proper conduits / channels above water level. In pump area and near the pool filtration plant.	  
TKT-00024	05 Jun 26	Common Area / B-1005	Sagar Thakare	Common Area	Critical	ASSIGNED	Cleaning needs to be done in kitchen duct on 1st floor and access to 1st floor duct For all Wings also where is the access to these	 
TKT-00134	12 Jul 26	Tower B / B-405	Nikhil Shintre	Common Area	High	ASSIGNED	Fire Exit staircase near 4th floor - Granite / Marble for the steps is broken at multiple places	
TKT-00080	20 Jun 26	Tower B / B-901	Dadasaheb S	Lift	High	ASSIGNED	Some basic lift settings appear to be missing or need adjustment: 1. Double-tap to cancel a floor call is not working. 2. The touch buttons are overly sensitive; even slight body contact can trigger multiple floor selections. 3. Not sure if the occupancy sensor is enabled. The cabin lights and fan should turn off when the lift is unoccupied. Currently, the fan can be heard running from outside even when the lift is empty.	
TKT-00077	18 Jun 26	Tower A / A1101	Prakash Yelwande	Common Area	High	ASSIGNED	Request to install pigeon nets and get exterior wall fixes. Pigion dropping, looks worst from our kitchen exactly opposite to kitchen of A1101,the wall in duct, kindly repaint without fail as we will need to see it life long and apply pegion nets at the earliest to avoid this	
TKT-00133	13 Jun 26	Common Area	Assessment 13th June	Civil	High	ASSIGNED	Cleanliness of ducts and common spaces before handover	
TKT-00132	13 Jun 26	Common Area	Assessment 13th June	Civil	High	ASSIGNED	Water Seepage This is one instance similar to that 20+ instances were already shared which are common due to leakage from ground floor. No proper grouting is done.	
TKT-00130	13 Jun 26	Common Area	Assessment 13th June	Civil	High	ASSIGNED	Duct Fixes Grouting/Drainage Check/Cleaning Grouting work is of serious concern in all common spaces	  
TKT-00127	13 Jun 26	Common	Assessment 13th June	Civil	High	ASSIGNED	Wall Cracks behind composting plant. In	   



Ticket ID	Submitted	Tower / Unit	Resident	Category	Severity	Status	Description	Photos
		Area					general across the society need to be checked	   
TKT-00105	13 Jun 26	C	Assessment 13th June	Civil	High	ASSIGNED	Tile Broken (C). Tiles across all the terraces and common spaces have to be replaced.	   
TKT-00102	13 Jun 26	Common Area	Assessment 13th June	Plumbing	High	ASSIGNED	Water seepage – Plumbing tank leaky near water pump are	   
TKT-00101	13 Jun 26	C	Assessment 13th June	Plumbing	High	ASSIGNED	Water level terrace C tower. This is important as water gets clogged.	
TKT-00095	13 Jun 26	Common Area	Assessment 13th June	Plumbing	High	ASSIGNED	Pump cover fire fighting cover. This is must as pump could be damaged due to water.	   
TKT-00088	13 Jun 26	Common Area	Assessment 13th June	General	High	ASSIGNED	Security Gate 2: Cabin is required. It can be possibly placed adjacent to parking exit.	
TKT-00087	13 Jun 26	A	Assessment 13th June	Civil	High	ASSIGNED	A Wing Service lift marble crack change required. This is just one example. All marbles inside the lift and at the footrest outside lift have to be checked and replace the cracked one. Proper filling to be done to avoid cracks.	   
TKT-00086	13 Jun 26	Common Area	Assessment 13th June	Utilities	High	ASSIGNED	STP Operation Room – Working/Finishing. Cleaning and Maintain it after all required installation is done.	
TKT-00083	13 Jun 26	Common Area	Assessment 13th June	Civil	High	ASSIGNED	Below pool area paint patches required. This patch work applicable across all the sections where drainage pipes core cutting is done. Cement is applied and left as is. Needs to be patched properly and painted.	   
TKT-00075	11 Jun 26	Common Area	Assessment 6th June	Civil	High	ASSIGNED	Provide a proper cover mechanism over the swimming-pool motor.	   

Ticket ID	Submitted	Tower / Unit	Resident	Category	Severity	Status	Description	Photos
TKT-00073	11 Jun 26	Common Area	Assessment 6th June	Amenities	High	ASSIGNED	(Starter box) Complete and commission the starter box for the swimming pool (near the water filtration unit).	 
TKT-00072	11 Jun 26	Common Area	Assessment 6th June	Amenities	High	ASSIGNED	(Baby pool demarcation) Mark a clear demarcation for the kids' section of the pool. Add steel rods or raise the wall.	
TKT-00070	11 Jun 26	Common Area	Assessment 6th June	Amenities	High	ASSIGNED	Complete / install the dais sheet (stage / podium covering) — pending item. Pool Area. Similarly on the garden area.	
TKT-00065	08 Jun 26	Common Area / C 702	Dhyanashloka Yabaluri	Common Area	High	ASSIGNED	Need 2 mirrors at the exit gate on each side of the exit as you cannot see while exiting if any vehicles are coming from either side	
TKT-00063	08 Jun 26	Common Area / B-201	Raj Thakker	Electrical	High	ASSIGNED	Loose wires on the floor and open electric boards and switches in all the 3 blds	    
TKT-00059	08 Jun 26	Common Area / C804	Hemant Deshmukh	Civil	High	ASSIGNED	Exit gate ramp out side gate not properly done. Concrete broken	
TKT-00056	08 Jun 26	Common Area	Assessment 6th June	Miscellaneous	High	ASSIGNED	Proper cleaning is required since moslty its because of construction remains on. Proper cleaning is required across the society. For the handover. Common spaces should be given equivalent focus similar to how builder does to a individual flat.	
TKT-00053	08 Jun 26	Common Area	Assessment 6th June	Miscellaneous	High	ASSIGNED	Provide warranty and guarantee certificates for the Diesel Generator.	
TKT-00052	08 Jun 26	Common Area	Assessment 6th June	Miscellaneous	High	ASSIGNED	Hand over M2M (machine-to-machine / monitoring) system details for the Diesel Generator.	


Ticket ID	Submitted	Tower / Unit	Resident	Category	Severity	Status	Description	Photos
TKT-00047	08 Jun 26	Common Area	Assessment 6th June	Civil	High	ASSIGNED	Grouting must be fixed at all locations before painting is done.	
TKT-00044	07 Jun 26	Common Area	Assessment 6th June	Miscellaneous	High	ASSIGNED	Open grills at the pillar in the lower basement — risky; close them.	
TKT-00037	07 Jun 26	Tower C	Assessment 6 June	Electrical	High	ASSIGNED	Provide casing for open earthing wires. Observed at the new C-Wing stack parking adjacent to the C-Wing interior entrance.	
TKT-00036	07 Jun 26	Common Area	Assessment 6 June	Electrical	High	ASSIGNED	Provide proper frame casing / conduits for all exposed wiring. Electrical – Wire casing / conduits. Applicable for Pump Area, Electrical Meter area all three towers, Parking Roofs	
TKT-00034	07 Jun 26	Common Area	Assessment 6 June	Civil	High	ASSIGNED	Re-do waterproofing on façade areas — leakage observed during rain; not properly done. The black glue (bituminous sealant) must be applied properly.	 
TKT-00033	07 Jun 26	Common Area	Assessment 6 June	Common Area	High	ASSIGNED	Build the square wall around the tree compound.	
TKT-00031	07 Jun 26	Common Area	Assessment 6 June	Miscellaneous	High	ASSIGNED	Install pigeon nets at the top of the inter-wing ducts: A–B, B–B, B–C. Applicable for all the towers.	
TKT-00029	07 Jun 26	Tower B	Assessment 6 June	Common Area	High	ASSIGNED	Provide a proper water-line access point in the flooring of the duct. Needs to be widened and proper grouting. This shall also be applicable in duct areas between A-B and B-C	
TKT-00027	07 Jun 26	Common Area	Assessment 6 June	Civil	High	ASSIGNED	Cover the triangular openings (4 nos.) along the driveway leading to the lower basement. • Prevents children from accessing the driveway. • Prevents rainwater (from the top / sides of the swimming-pool area above) from falling onto the filtration motor below.	
TKT-00122	06 Jun 26		Assessment 6th June	Common Area	High	ASSIGNED	Composting machine to be functional and its operation to be explained to Society Manager and at least 5 identified members of the society.	


Ticket ID	Submitted	Tower / Unit	Resident	Category	Severity	Status	Description	Photos
TKT-00120	06 Jun 26		Assessment 6th June	Civil	High	ASSIGNED	Complete painting works in the lower-ground basement, including: • Entry area • Parking area • Ceiling	     
TKT-00117	06 Jun 26		Assessment 6th June	Common Area	High	ASSIGNED	The marked area must NOT be allotted as parking, since it is a turning point for vehicles entering the building. Re-plan and exclude this area from parking. This is serious and shall cause trouble to the residents and breach the safety. This is at the basement just outside the pump room.	
TKT-00116	06 Jun 26		Assessment 6th June	Civil	High	ASSIGNED	Water leakage observed near the building entry point. Identify the source and rectify. In general leakage has to be fixed in all identified areas.	
TKT-00114	06 Jun 26		Assessment 6th June	Plumbing	High	ASSIGNED	One drainage line near the pump area has been cleaned — verify and confirm that the remaining lines are also clear.	
TKT-00113	06 Jun 26		Assessment 6th June	Civil	High	ASSIGNED	Water seepage at 2 locations in the pump area. Investigate the source and rectify (waterproofing).	
TKT-00112	06 Jun 26		Assessment 6th June	Electrical	High	ASSIGNED	Loose wiring observed in the electrical panel near the LG-floor pump area. Address and terminate the wiring properly.	
TKT-00110	06 Jun 26		Assessment 6th June	Miscellaneous	High	ASSIGNED	Hand over the following for the submersible pump: • Power rating details • AMC contract • Warranty certificate • Vendor / service contact details	
TKT-00107	06 Jun 26		Assessment 6th June	Plumbing	High	ASSIGNED	Non-Return Valve (NRV) on the balancing-tank line has not been provided. Install it.	
TKT-00022	05 Jun 26	Common	Y Manjula Rao	Common Area	High	ASSIGNED	EXIT Gate. Auditor: There are multiple issues	


Ticket ID	Submitted	Tower / Unit	Resident	Category	Severity	Status	Description	Photos
		Area / C-702					at the exit gate Proper ramping needs to be done Gate operation is troublesome. It is not smooth as reported by security. Kindly fix it.	
TKT-00007	25 May 26	Tower B	Maitreya	Lift	High	ASSIGNED	Tower B Service lift	
TKT-00006	10 May 26	Tower A / A-904	Chiranjit Banerjee	Lift	High	ASSIGNED	Left side lift back side fan	
TKT-00001	09 May 26	Tower B / B-805	Maitreya	Plumbing	High	ASSIGNED	Water Leakagefrom hanging pipes on the roof in the UG Tower B parking	
TKT-00082	30 Jun 26	Common Area / B-901	Dadasaheb Salunke	Fire Safety	Medium	ASSIGNED	Location - Basement parking (Infront of A-wing lift door at basement) Pathways to the lifts should be removed. It limits space and can cause damage to parked vehicle as well. Remove this parking.	
TKT-00131	13 Jun 26	Common Area	Assessment 13th June	Civil	Medium	ASSIGNED	Tiles and Marble Fixes in general across the society in common areas and lifts and pathways marbles are broken and need to be fixed.	 
TKT-00129	13 Jun 26	Common Area	Assessment 13th June	Civil	Medium	ASSIGNED	Patches and Undone Sections	      
TKT-00104	13 Jun 26	Common Area	Assessment 13th June	Plumbing	Medium	ASSIGNED	Air pipe WC pipe extend heights	 
TKT-00103	13 Jun 26	Common Area	Assessment 13th June	Plumbing	Medium	ASSIGNED	Hanging plumbing pipe at the terrace of A building.	
TKT-00093	13 Jun 26	A	Assessment 13th June	Electrical	Medium	ASSIGNED	Electrical points left open in Terrace (A)	


Ticket ID	Submitted	Tower / Unit	Resident	Category	Severity	Status	Description	Photos
TKT-00089	13 Jun 26	A	Assessment 13th June	Civil	Medium	ASSIGNED	A Building Fire Door Handle missing	
TKT-00085	13 Jun 26	Common Area	Assessment 13th June	Electrical	Medium	ASSIGNED	Open Electrical points near gym area possible for lights. Adjacent to pathways. They were planned for lamps but currently left wideopen and may cause electrical issues due to open wires. Specially during rains.	 
TKT-00069	11 Jun 26	Common Area	Assessment 6th June	Civil	Medium	ASSIGNED	Carry out silicone grouting at all locations where glass is fitted (especially C-Wing / Main Entrance / all tower gates / Pool Area).	
TKT-00068	11 Jun 26	Common Area	Assessment 6th June	Civil	Medium	ASSIGNED	(Storage Rooms) Complete painting of the C-Wing and Main Entrance storage rooms.	 
TKT-00064	08 Jun 26	Tower A / A- 701	Gulzarsingh Virdi	Civil	Medium	ASSIGNED	Common bathroom tile which has switchboard does not have concrete behind it. Hollow tile.	
TKT-00061	08 Jun 26	Common Area / B-201	Raj Thakker	Miscellaneous	Medium	ASSIGNED	Common areas in A, B, C BDGS	    
TKT-00060	08 Jun 26	Common Area / B-201	Raj Thakker	Miscellaneous	Medium	ASSIGNED	Swimming pool area	    
TKT-00057	08 Jun 26	Common Area / B-201	Raj Thakker	Electrical	Medium	ASSIGNED	Common areas. Provide proper wire casings. All loose wires.	  

Ticket ID	Submitted	Tower / Unit	Resident	Category	Severity	Status	Description	Photos
TKT-00054	08 Jun 26	Common Area	Assessment 6th June	Lift	Medium	ASSIGNED	Lifts in A-Wing and C-Wing are not operating in sync. Configure synchronisation logic so that idle lifts are not called unnecessarily, thereby reducing energy consumption.	
TKT-00048	08 Jun 26	Common Area	Assessment 6th June	Civil	Medium	ASSIGNED	Apply rubber paint / anti-skid coating on all driveways — ground floor and lower basement.	
TKT-00043	07 Jun 26	Common Area	Assessment 6th June	Electrical	Medium	ASSIGNED	Electric light hanging on one side, broken — lower basement below B-Wing. Re-fix.	
TKT-00042	07 Jun 26	Common Area	Assessment 6th June	Civil	Medium	ASSIGNED	Broken tiles and unfinished civil work in the space — fix.	
TKT-00041	07 Jun 26	Common Area	Assessment 6th June	Civil	Medium	ASSIGNED	Civil – Broken ceiling support - Broken ceiling support to be repaired.	
TKT-00038	07 Jun 26	Common Area	Assessment 6 June	Electrical	Medium	ASSIGNED	Seal and finish all electrical cable entry points into the building.	
TKT-00035	07 Jun 26	Common Area	Assessment 6 June	Civil	Medium	ASSIGNED	Apply anti-rust primer / paint on all metal surfaces (railings, grills, STP area grills) before final painting. Applicable across the society.	
TKT-00026	06 Jun 26	Tower B / B 1003	Sunil Tiwari	Common Area	Medium	ASSIGNED	10th floor lobby roof has damages. Open wiring seen above passage light. This is in general across society and must be fixed.	
TKT-00124	06 Jun 26		Assessment 6th June	Common Area	Medium	ASSIGNED	Cover missing behind the compost machine — install.	
TKT-00111	06 Jun 26		Assessment 6th June	Plumbing	Medium	ASSIGNED	Provide drainage grills in the pump section / pump room wherever necessary, and near the filtration pump.	
TKT-00109	06 Jun 26		Assessment 6th June	Plumbing	Medium	ASSIGNED	Storm-water / surface drainage grills are pending at several end-points. Install them.	

Ticket ID	Submitted	Tower / Unit	Resident	Category	Severity	Status	Description	Photos
							One observed near the filtration unit.	
TKT-00108	06 Jun 26		Assessment 6th June	Electrical	Medium	ASSIGNED	The submersible pump near the swimming-pool balancing tank has wires lying loose. Secure the wiring with proper covering / conduit.	
TKT-00023	05 Jun 26	Tower B / B-1204	Shailja Kumar	Common Area	Medium	ASSIGNED	Outside B-1204 Need to fix the flooring. Auditor: In General Grouting work of lobby's/ducts and marble fixes are required to be done. These are basic things.	    
TKT-00019	04 Jun 26	Tower A / A-1302	Sanket Ranade	Civil	Medium	ASSIGNED	Refugee area exterior on 13th floor paint washed away in first rain Though Painting should be redone. Since at many places across the society due to construction it got damaged. To go through across society and fix both interior and exterior paint patches.	
TKT-00018	04 Jun 26	Tower B / B-1003	Sunil Tiwari	Amenities	Medium	ASSIGNED	Parking is full of construction garbage and incomplete. The stilt Parking is not level in many places In general parking related markings, leakages, and proper lights above the parkings. Fix hanging lights in parking check both basement and ground level roofs.	
TKT-00017	04 Jun 26	Tower A / A-1302	Sanket Ranade	Plumbing	Medium	ASSIGNED	Drain pipe not fitted with wire, can be seen from roof. Also small patch not painted. Need to add U clip. This is general and must be checked across all terraces and to be fixed from plumbing side.	
TKT-00016	04 Jun 26	Tower A / A-201	Manasadevi P T	Amenities	Medium	ASSIGNED	The commode of washroom near the pool are directly visible from the lower floors of wing A. Since these washrooms will be used extensively. the doors are likely to remain open most of the time when residents start using the facility. Kindly arrange for some visual privacy either in the form of landscaping with some climbers or some similar infrastructure.	 
TKT-00013	02 Jun 26	Tower B / B 604	Saraswati Chandrashekhar	Common Area	Medium	ASSIGNED	Common area , in the dry balcony duct has a lot of wall chip offs and is extremely dirty with plastic bags ,etc .	 

Ticket ID	Submitted	Tower / Unit	Resident	Category	Severity	Status	Description	Photos
TKT-00012	01 Jun 26	Tower A / A-904	Chiranjit Banerjee	Common Area	Medium	ASSIGNED	Entry floor tiles has orange colour symmetrical stains at four places	
TKT-00011	01 Jun 26	Tower C / C 1103	Dattaraj Joshi	Electrical	Medium	ASSIGNED	Switch over to DG is not happening as the wiring id done properly woth MCB	
TKT-00003	10 May 26	Common Area	Maitreya	Security	Medium	ASSIGNED	Society compound wall on the east side needs to build there is a small passage for easy entry.	
TKT-00002	09 May 26	Tower B / B-805	Maitreya	Common Area	Medium	ASSIGNED	Railings of the stairs are getting rusted and requires painting. All towers.	
TKT-00079	20 Jun 26	Common Area / B-901	Dadasaheb Salunke	Common Area	Low	ASSIGNED	Add proper iron casing to the plumbing pipes which could be damaged because of vehicle movement through the driveways. With reference to the attached image, the passage area behind the B-Wing lift lobby is currently being used for two-wheeler parking. Several plumbing pipes are installed along the wall in this area, and there is a high risk of damage to these pipes due to contact from front tyres of parked two-wheelers, particularly from tyres and vehicle movement. It is recommended to either: 1. Prohibit two-wheeler parking in this passage area, or 2. Protect the plumbing pipes by installing a suitable steel safety grid/guard along the wall.	
TKT-00128	13 Jun 26	Common Area	Assessment 13th June	Electrical	Low	ASSIGNED	Open ElectricalWirings must be fixed across the society	    
TKT-00126	13 Jun 26	Common Area	Assessment 13th June	Plumbing	Low	ASSIGNED	Gate and Functioning of Staff Toilet All proper plumbing should be fixed and functional. Make sure it has sufficient water storage for toilets for staff.	
TKT-00106	13 Jun 26	C	Assessment 13th June	General	Low	ASSIGNED	C Wing B U Cup. U clips support to plimbing	

Ticket ID	Submitted	Tower / Unit	Resident	Category	Severity	Status	Description	Photos
							pipes missing. This must be inspected and provided wherever missing.	
TKT-00100	13 Jun 26	Common Area	Assessment 13th June	Plumbing	Low	ASSIGNED	Club House Toilet flush – Toilet (1) choked. Need to inspect and fix the plumbing related in all the toilets in common spaces. For leakages, ball sockets, commode leakage etc	
TKT-00099	13 Jun 26	C	Assessment 13th June	General	Low	ASSIGNED	Wire mesh safety C wing. Electricity Supply door wires are messed and crumbled may cause issues. Need to check and cleaned properly. Near C-204	
TKT-00094	13 Jun 26	Common Area	Assessment 13th June	General	Low	ASSIGNED	Supporter gas O cap broken and are required at all pipes at the top of each tower. Applicable for all towers.	 
TKT-00067	09 Jun 26	Common Area / A-201	Manasadevi P T	Common Area	Low	ASSIGNED	NO PARKING' road barricades near the gates so that path is clear for vehicles in and out of society. Foot path between society entry and exit gate. Currently it is unfinished and not suitable for pedestrians.	
TKT-00066	08 Jun 26	Common Area	Assessment 6th June	Security	Low	ASSIGNED	Fan at security room front gate sheet at the front side glass in security room - Gate at security room.	  
TKT-00058	08 Jun 26	Tower B / B-201	Raj Thakker	Common Area	Low	ASSIGNED	Basement parking area Patches/Paint/Proper wise casings at parking	   
TKT-00055	08 Jun 26	Common Area	Assessment 6th June	Miscellaneous	Low	ASSIGNED	Door of the STP should be locked, since it has open drains and is risky. Provide proper keys.	
TKT-00046	08 Jun 26	Common Area	Assessment 6th June	Electrical	Low	ASSIGNED	provide a protective cover / guard if possible	
TKT-00045	08 Jun 26	Common Area	Assessment 6th June	Miscellaneous	Low	ASSIGNED	Staircase to the garden area from A-Building has been removed; people may attempt to jump — install a barrier / restore the staircase.	
TKT-00040	07 Jun 26	Common Area	Assessment 6th June	Civil	Low	ASSIGNED	Pool toilet – Wall holes / paint - Two holes at the pool toilet to be filled & painted.	

Ticket ID	Submitted	Tower / Unit	Resident	Category	Severity	Status	Description	Photos
TKT-00039	07 Jun 26	Tower C	Assessment 6 June	Civil	Low	ASSIGNED	Complete painting of the C-Wing and Main Entrance storage rooms. Storage room painting. At C wing and Main Entrance	
TKT-00032	07 Jun 26	Common Area	Assessment 6 June	Security	Low	ASSIGNED	Complete the compound wall along with wire fencing where pending. Near Composting machine. Fencing to enhance the periphery of the society wall	
TKT-00028	07 Jun 26	Tower B	Assessment 6 June	Miscellaneous	Low	ASSIGNED	Provide a door-lock mechanism so that the room space created below the refuge area on the first floor (B-Wing only) can be used. Understand what that area is to be used for.	
TKT-00125	06 Jun 26		Assessment 6th June	Amenities	Low	ASSIGNED	Play area is incomplete / pending — complete it. Review once if no open joint which could harm children. Targeted only one age group should have been incorporate for 5-8 years as well. Point of improvement.	
TKT-00123	06 Jun 26		Assessment 6th June	Common Area	Low	ASSIGNED	Clean the compost area properly and fill it with mud. At the back side there are holes which could pave way for animals. Focus on cleaning part here.	
TKT-00025	05 Jun 26	Tower C / C703	Pratik	Common Area	Low	ASSIGNED	Clear all the construction material from the lower basement as soon as possible, it's risk for accident during parking Or place them in areas where no obstruction to passage or movement. Below B building back side in LG floor.	
TKT-00021	04 Jun 26	Tower B / B-503	Sweta Shailli	Miscellaneous	Low	ASSIGNED	Water pressure is quite low plus the drinking water (as when checked not there) - still not residing so don't know the exact issue. Auditor: In general kindly perform the pressure test check and see if any thing can be done to address pressure related issues ?	
TKT-00015	02 Jun 26	Tower B / A-1103	Dhananjay Ghogale	Common Area	Low	ASSIGNED	Outside lobby / driveway This is one of the patch similar to this across the society all undone patches must be fixed.	
TKT-00014	02 Jun 26	Common Area / A-1103	Dhananjay Ghogale	Common Area	Low	ASSIGNED	Shared wall of ev charging and transformer room Auditor: Check for the compliance stand point if access points can access the same wall as	

Ticket ID	Submitted	Tower / Unit	Resident	Category	Severity	Status	Description	Photos
							transformer room.	
TKT-00009	01 Jun 26	Tower C / C-1301	Shriyal Naik	Plumbing	Low	ASSIGNED	Water Pressure is very less. Water pressure pumps needs to be installed asap and this should be dependent on the occupancy	
TKT-00008	31 May 26	Common Area	Maitreya	Miscellaneous	Low	ASSIGNED	Shade in Electrical charging station uses currently thin sheet which is not reliable and prone to catch fire as it is near the charging point. It is recommended to get the tin shades.	
TKT-00005	10 May 26	Tower B	Maitreya	Common Area	Low	ASSIGNED	Refuge Area in tower B has a hollow passage, which enables the way for Pigeon. To limit that nets may be placed there	 
TKT-00004	10 May 26	Common Area / B-805	Maitreya	Electrical	Low	ASSIGNED	Need of electric light generator at out gate. At night it can be fatal while filling the fuel at dark. (Currently there is not wall or railing at the backside of generator facing Ramnadi)	