





Name	Value	Data Type	Scope
 Local:3:I		AB:1756_DI:I:0	Process_Output
Constant	No		
External Access:	Read/Write		
OPC UA Access:	None		
Local:3:I.Data.0	0	BOOL	
<i>SW_START - MainProgram/FuncRoutine - 2-A1(IREF,SW_START), 2-B1(MUL,MUL_01.EnableIn), 3-A1(IREF,SW_START), 3-B1(BOR,BOR_01.In1)</i>			
 Local:4:O		AB:1756_DO:O:0	Process_Output
Constant	No		
External Access:	Read/Write		
OPC UA Access:	None		
Local:4:O.Data.0	0	BOOL	
<i>PROCESS_OUTPUT - MainProgram/FuncRoutine - *3-E1(OREF,PROCESS_OUTPUT), 3-C1(TONR,TONR_01.EN)</i>			
 PROCESS_OUTPUT	0	BOOL	Process_Output
Process Output			
AliasFor:	Local:4:O.Data.0		
Base Tag:	Local:4:O.Data.0		
Constant	No		
External Access:	Read/Write		
OPC UA Access:	None		
<i>PROCESS_OUTPUT - MainProgram/FuncRoutine - *3-E1(OREF,PROCESS_OUTPUT), 3-C1(TONR,TONR_01.EN)</i>			
 SW_START	0	BOOL	Process_Output
START Momentary N.O. Pushbutton			
AliasFor:	Local:3:I.Data.0		
Base Tag:	Local:3:I.Data.0		
Constant	No		
External Access:	Read/Write		
OPC UA Access:	None		
<i>SW_START - MainProgram/FuncRoutine - 2-A1(IREF,SW_START), 2-B1(MUL,MUL_01.EnableIn), 3-A1(IREF,SW_START), 3-B1(BOR,BOR_01.In1)</i>			









Process_Output

Tag Listing	1
-------------------	---

MainTask

MainProgram

FuncHMI

Function Block Diagram	2
------------------------------	---

FuncRoutine

Function Block Diagram	3
------------------------------	---