
unit = 1: sensor readings as time series 



200 25 20 20 25

0 1580

25

0 0

644

642

25

O O

23.5

W32

T24

0

200

25

0 23.0

518.5519.0

T2

unit = 1: sensor readings as histogram

T30

1600

0

25

0

1400 1425

T50


0

200

0

14.5 15.0

P2



unit = 1: operational settings 0.0050 0.0004 104 0.0025 102 0.0002 0.0000 100 0.0000 -0.002598 -0.0002-0.005096 -0.0004100 200 100 200 100 200

