SAMPLE REPORT

Sample Home Inspections

Home Inspection Report

123 Sample Lane
Anytown, OH 45000
Inspection Date: 04/02/2025
Prepared for: Sample Client

This is a made-up sample for trying the "Add from Inspection Report" feature in Tallihaus. It isn't a real house, inspection or inspection company, and nothing in it is advice.

Summary

2.1.1 Roof - Coverings: Missing Shingles
2.2.1 Roof - Gutters & Downspouts: Debris In Gutters
3.1.1 Exterior - Siding, Flashing & Trim: Peeling Paint
3.2.1 Exterior - Decks, Porches & Steps: Loose Railing
4.1.1 Plumbing - Water Heater: Older Water Heater
4.2.1 Plumbing - Drain, Waste & Vent Systems: Slow Drain
5.1.1 Electrical - Receptacles: No GFCI Protection
5.2.1 Electrical - Smoke Detectors: Missing Smoke Detector
6.1.1 Heating - Furnace: Dirty Filter
7.1.1 Garage - Garage Door: Auto-Reverse Needs Adjustment

2: ROOF

Information

Coverings: Material

Asphalt Shingles

Limitations

The age of a roof is only an estimate. Roof leaks can happen at any time and should be evaluated by a qualified roofer.

Deficiencies

2.1.1 Coverings

MISSING SHINGLES

Recommendation

Two shingles were missing on the rear slope. Recommend a qualified roofer replace the missing shingles.

Recommendation

Contact a qualified roofing professional.

2.2.1 Gutters & Downspouts

DEBRIS IN GUTTERS

Maintenance Item

Leaves and debris have built up in the front gutters. Recommend cleaning so water drains away from the house.

Recommendation

Recommended DIY Project

3: EXTERIOR

Deficiencies

3.1.1 Siding, Flashing & Trim

PEELING PAINT

Recommendation

Paint was peeling on the window trim. Recommend scraping and painting to prevent wood rot.

Recommendation

Contact a qualified painter.

3.2.1 Decks, Porches & Steps

LOOSE RAILING

Safety Hazard or Major Deficiency

The rear deck stair railing was loose and could give way. Recommend a qualified contractor secure the railing for safety.

Recommendation

Contact a qualified professional.

4: PLUMBING

Deficiencies

4.1.1 Water Heater

OLDER WATER HEATER

Recommendation

The water heater is about 13 years old and near the end of its typical life. Monitor it and budget for replacement.

Recommendation

Recommend monitoring.

4.2.1 Drain, Waste & Vent Systems

SLOW DRAIN

Recommendation

The hall bathroom sink drained slowly. Recommend a plumber clear the drain.

Recommendation

Contact a qualified plumbing contractor.

5: ELECTRICAL

Deficiencies

5.1.1 Receptacles

NO GFCI PROTECTION

Safety Hazard or Major Deficiency

The bathroom outlets had no GFCI protection. Recommend a licensed electrician install GFCI protection for safety.

Recommendation

Contact a qualified electrical contractor.

5.2.1 Smoke Detectors

MISSING SMOKE DETECTOR

Recommendation

There was no smoke detector in the second bedroom. Recommend installing one in every bedroom.

Recommendation

Recommended DIY Project

6: HEATING

Deficiencies

6.1.1 Furnace

DIRTY FILTER

Maintenance Item

The furnace filter was dirty. Recommend replacing it now and every 1 to 3 months.

Recommendation

Recommended DIY Project

7: GARAGE

Deficiencies

7.1.1 Garage Door

AUTO-REVERSE NEEDS ADJUSTMENT

Recommendation

The garage door did not reverse when it met resistance. Recommend a garage door technician adjust the opener.

Recommendation

Contact a qualified garage door contractor.

Standards of Practice

This sample follows the general layout of a home inspection report. The inspector is not required to determine the remaining life of any system. This report is not a guarantee or warranty.