WORK INSTRUCTION

Document ID: DOC-0002694
Project: PRJ-021
Uploaded on: 2026-05-07
Uploaded by: user060
Export class: EAR99

Assembly of P-103212 at plant PLT03

Part Number: P-103212
Revision: A.1
Plant: PLT03
Station: ST-19
Torque (Nm): 20
Cycle time (s): 266

Step 1: Fit fasteners

Step 2: Move to next station

Step 3: Inspect incoming part

Step 4: Inspect incoming part

Step 5: Clean mating surface

Step 6: Record result

Step 7: Torque to specification

Step 8: Record result

Assembly of P-100202 at plant PLT01

Part Number: P-100202
Revision: B.1
Plant: PLT01
Station: ST-73
Torque (Nm): 5
Cycle time (s): 225

Step 1: Fit fasteners

Step 2: Move to next station

Step 3: Torque to specification

Step 4: Torque to specification

Step 5: Torque to specification

Step 6: Record result

Step 7: Clean mating surface

Assembly of P-100282 at plant PLT04

Part Number: P-100282
Revision: A.1
Plant: PLT04
Station: ST-59

Torque (Nm): 20
Cycle time (s): 187

Step 1: Fit fasteners

Step 2: Record result

Step 3: Torque to specification

Step 4: Move to next station

Step 5: Move to next station