WORK INSTRUCTION

Document ID: DOC-0001638
Project: PRJ-034
Uploaded on: 2024-12-25
Uploaded by: user089
Export class: EAR99

Assembly of P-101446 at plant PLT04

Part Number: P-101446
Revision: A.1
Plant: PLT04
Station: ST-67
Torque (Nm): 8
Cycle time (s): 106

Step 1: Record result

Step 2: Visual check

Step 3: Fit fasteners

Step 4: Visual check

Step 5: Visual check

Step 6: Fit fasteners

Step 7: Fit fasteners

Assembly of P-101314 at plant PLT02

Part Number: P-101314
Revision: A.1
Plant: PLT02
Station: ST-19
Torque (Nm): 12
Cycle time (s): 163

Step 1: Inspect incoming part

Step 2: Clean mating surface

Step 3: Torque to specification

Step 4: Record result

Step 5: Inspect incoming part

Step 6: Visual check

Step 7: Fit fasteners

Step 8: Visual check