WORK INSTRUCTION

Document ID: DOC-0001566
Project: PRJ-022
Uploaded on: 2024-11-17
Uploaded by: user073
Export class: EAR99

Assembly of P-101150 at plant PLT01

Part Number: P-101150
Revision: A.1
Plant: PLT01
Station: ST-83
Torque (Nm): 5
Cycle time (s): 244

Step 1: Clean mating surface

Step 2: Clean mating surface

Step 3: Move to next station

Step 4: Record result

Step 5: Torque to specification

Assembly of P-100710 at plant PLT03

Part Number: P-100710
Revision: A.1
Plant: PLT03
Station: ST-43
Torque (Nm): 5
Cycle time (s): 197

Step 1: Record result

Step 2: Move to next station

Step 3: Inspect incoming part

Step 4: Visual check

Step 5: Move to next station

Step 6: Record result

Step 7: Clean mating surface

Step 8: Inspect incoming part