WORK INSTRUCTION

Document ID: DOC-0001228
Project: PRJ-039
Uploaded on: 2024-06-22
Uploaded by: user082
Export class: EAR99

Assembly of P-102040 at plant PLT01

Part Number: P-102040
Revision: A.1
Plant: PLT01
Station: ST-52
Torque (Nm): 5
Cycle time (s): 173

Step 1: Visual check

Step 2: Torque to specification

Step 3: Record result

Step 4: Fit fasteners

Step 5: Torque to specification

Step 6: Inspect incoming part

Assembly of P-100647 at plant PLT02

Part Number: P-100647
Revision: A.1
Plant: PLT02
Station: ST-42
Torque (Nm): 5
Cycle time (s): 30

Step 1: Move to next station

Step 2: Torque to specification

Step 3: Move to next station

Step 4: Clean mating surface

Step 5: Record result

Step 6: Apply thread locker

Step 7: Apply thread locker

Step 8: Torque to specification

Assembly of P-101160 at plant PLT04

Part Number: P-101160
Revision: A.1
Plant: PLT04
Station: ST-12
Torque (Nm): 20

Cycle time (s): 90

Step 1: Record result

Step 2: Apply thread locker

Step 3: Record result

Step 4: Torque to specification

Step 5: Torque to specification