WORK INSTRUCTION

Document ID: DOC-0001287
Project: PRJ-024
Uploaded on: 2024-07-22
Uploaded by: user180
Export class: EAR99

Assembly of P-100525 at plant PLT02

Part Number: P-100525
Revision: A.1
Plant: PLT02
Station: ST-51
Torque (Nm): 20
Cycle time (s): 113

Step 1: Visual check

Step 2: Apply thread locker

Step 3: Inspect incoming part

Step 4: Apply thread locker

Step 5: Apply thread locker

Step 6: Fit fasteners

Step 7: Torque to specification

Assembly of P-102151 at plant PLT01

Part Number: P-102151
Revision: A.1
Plant: PLT01
Station: ST-24
Torque (Nm): 8
Cycle time (s): 283

Step 1: Torque to specification

Step 2: Clean mating surface

Step 3: Apply thread locker

Step 4: Visual check

Step 5: Visual check

Step 6: Apply thread locker

Step 7: Clean mating surface

Assembly of P-100188 at plant PLT04

Part Number: P-100188
Revision: A.1
Plant: PLT04
Station: ST-55
Torque (Nm): 12

Cycle time (s): 130

Step 1: Visual check

Step 2: Torque to specification

Step 3: Torque to specification

Step 4: Visual check

Step 5: Apply thread locker