WORK INSTRUCTION

Document ID: DOC-0002377
Project: PRJ-006
Uploaded on: 2025-12-12
Uploaded by: user167
Export class: EAR99

Assembly of P-101206 at plant PLT01

Part Number: P-101206
Revision: A.1
Plant: PLT01
Station: ST-41
Torque (Nm): 2.5
Cycle time (s): 65

Step 1: Clean mating surface

Step 2: Torque to specification

Step 3: Record result

Step 4: Move to next station

Step 5: Visual check

Step 6: Inspect incoming part

Step 7: Visual check

Step 8: Torque to specification

Assembly of P-102115 at plant PLT01

Part Number: P-102115
Revision: B.1
Plant: PLT01
Station: ST-31
Torque (Nm): 2.5
Cycle time (s): 287

Step 1: Inspect incoming part

Step 2: Visual check

Step 3: Fit fasteners

Step 4: Record result

Step 5: Record result

Step 6: Clean mating surface

Step 7: Inspect incoming part

Step 8: Inspect incoming part

Assembly of P-103780 at plant PLT01

Part Number: P-103780
Revision: A.1
Plant: PLT01

Station:	ST-37
Torque (Nm):	12
Cycle time (s):	223

Step 1: Torque to specification

Step 2: Record result

Step 3: Fit fasteners

Step 4: Move to next station

Step 5: Torque to specification

Step 6: Torque to specification

Step 7: Inspect incoming part

Step 8: Torque to specification