# WORK INSTRUCTION

**Document ID:** DOC-0002658
**Project:** PRJ-037
**Uploaded on:** 2026-04-17
**Uploaded by:** user020
**Export class:** EAR99

## Assembly of P-100996 at plant PLT02

**Part Number:** P-100996
**Revision:** B.1
**Plant:** PLT02
**Station:** ST-25
**Torque (Nm):** 8
**Cycle time (s):** 171

Step 1: Clean mating surface

Step 2: Torque to specification

Step 3: Visual check

Step 4: Visual check

Step 5: Inspect incoming part

Step 6: Move to next station

## Assembly of P-102114 at plant PLT01

**Part Number:** P-102114
**Revision:** A.1
**Plant:** PLT01
**Station:** ST-72
**Torque (Nm):** 2.5
**Cycle time (s):** 243

Step 1: Clean mating surface

Step 2: Record result

Step 3: Inspect incoming part

Step 4: Record result

Step 5: Move to next station

Step 6: Fit fasteners

Step 7: Inspect incoming part

Step 8: Move to next station

## Assembly of P-104110 at plant PLT04

**Part Number:** P-104110
**Revision:** A.1
**Plant:** PLT04
**Station:** ST-65
**Torque (Nm):** 2.5

**Cycle time (s):** 88

Step 1: Clean mating surface

Step 2: Fit fasteners

Step 3: Inspect incoming part

Step 4: Apply thread locker

Step 5: Fit fasteners

Step 6: Move to next station

Step 7: Inspect incoming part