ITAR CONTROLLED - USML CATEGORY XIX

WORK INSTRUCTION

Document ID: DOC-0002135
Project: PRJ-012
Uploaded on: 2025-08-10
Uploaded by: user175
Export class: ITAR-USML-XIX

Assembly of P-101404 at plant PLT04

Part Number: P-101404
Revision: A.1
Plant: PLT04
Station: ST-90
Torque (Nm): 20
Cycle time (s): 114

Step 1: Fit fasteners

Step 2: Move to next station

Step 3: Record result

Step 4: Apply thread locker

Step 5: Clean mating surface

Step 6: Visual check

Assembly of P-100569 at plant PLT03

Part Number: P-100569
Revision: A.1
Plant: PLT03
Station: ST-35
Torque (Nm): 20
Cycle time (s): 76

Step 1: Visual check

Step 2: Move to next station

Step 3: Visual check

Step 4: Move to next station

Step 5: Visual check

Step 6: Fit fasteners

Assembly of P-100897 at plant PLT02

Part Number: P-100897
Revision: A.1
Plant: PLT02
Station: ST-99
Torque (Nm): 20

Cycle time (s): 283

Step 1: Fit fasteners

Step 2: Inspect incoming part

Step 3: Torque to specification

Step 4: Inspect incoming part

Step 5: Fit fasteners

Step 6: Clean mating surface

Step 7: Fit fasteners