WORK INSTRUCTION

Document ID: DOC-0002165
Project: PRJ-035
Uploaded on: 2025-09-03
Uploaded by: user160
Export class: EAR99

Assembly of P-101136 at plant PLT03

Part Number: P-101136
Revision: B.1
Plant: PLT03
Station: ST-41
Torque (Nm): 2.5
Cycle time (s): 40

Step 1: Move to next station

Step 2: Visual check

Step 3: Inspect incoming part

Step 4: Visual check

Step 5: Visual check

Step 6: Record result

Step 7: Record result

Assembly of P-102488 at plant PLT02

Part Number: P-102488
Revision: A.1
Plant: PLT02
Station: ST-89
Torque (Nm): 20
Cycle time (s): 233

Step 1: Inspect incoming part

Step 2: Move to next station

Step 3: Apply thread locker

Step 4: Torque to specification

Step 5: Inspect incoming part

Step 6: Apply thread locker

Step 7: Torque to specification

Assembly of P-102281 at plant PLT04

Part Number: P-102281
Revision: A.1
Plant: PLT04
Station: ST-32
Torque (Nm): 2.5

Cycle time (s): 174

Step 1: Apply thread locker

Step 2: Visual check

Step 3: Torque to specification

Step 4: Clean mating surface

Step 5: Visual check

Step 6: Visual check

Step 7: Clean mating surface

Step 8: Torque to specification