EXPORT CONTROLLED - ECCN 3A001

WORK INSTRUCTION

Document ID: DOC-0001376
Project: PRJ-033
Uploaded on: 2024-08-27
Uploaded by: user057
Export class: ECCN-3A001

Assembly of P-100440 at plant PLT04

Part Number: P-100440
Revision: B.1
Plant: PLT04
Station: ST-89
Torque (Nm): 5
Cycle time (s): 35

Step 1: Visual check

Step 2: Torque to specification

Step 3: Clean mating surface

Step 4: Inspect incoming part

Step 5: Move to next station

Step 6: Clean mating surface

Assembly of P-101988 at plant PLT04

Part Number: P-101988
Revision: A.1
Plant: PLT04
Station: ST-85
Torque (Nm): 20
Cycle time (s): 196

Step 1: Record result

Step 2: Move to next station

Step 3: Visual check

Step 4: Move to next station

Step 5: Record result

Step 6: Move to next station