WORK INSTRUCTION

Document ID: DOC-0003036
Project: PRJ-027
Uploaded on: 2026-10-24
Uploaded by: user158
Export class: EAR99

Assembly of P-104291 at plant PLT04

Part Number: P-104291
Revision: A.1
Plant: PLT04
Station: ST-97
Torque (Nm): 5
Cycle time (s): 184

Step 1: Visual check

Step 2: Clean mating surface

Step 3: Torque to specification

Step 4: Visual check

Step 5: Torque to specification

Step 6: Clean mating surface

Step 7: Torque to specification

Assembly of P-100583 at plant PLT04

Part Number: P-100583
Revision: A.1
Plant: PLT04
Station: ST-54
Torque (Nm): 5
Cycle time (s): 107

Step 1: Visual check

Step 2: Move to next station

Step 3: Fit fasteners

Step 4: Apply thread locker

Step 5: Inspect incoming part

Assembly of P-100276 at plant PLT03

Part Number: P-100276
Revision: A.1
Plant: PLT03
Station: ST-41
Torque (Nm): 2.5
Cycle time (s): 205

Step 1: Move to next station

Step 2: Apply thread locker

Step 3: Record result

Step 4: Clean mating surface

Step 5: Move to next station