ITAR CONTROLLED - USML CATEGORY XIX

# WORK INSTRUCTION

**Document ID:** DOC-0002458
**Project:** PRJ-012
**Uploaded on:** 2026-01-17
**Uploaded by:** user185
**Export class:** ITAR-USML-XIX

## Assembly of P-100176 at plant PLT03

**Part Number:** P-100176
**Revision:** C.1
**Plant:** PLT03
**Station:** ST-30
**Torque (Nm):** 2.5
**Cycle time (s):** 71

Step 1: Move to next station

Step 2: Clean mating surface

Step 3: Torque to specification

Step 4: Visual check

Step 5: Apply thread locker

Step 6: Inspect incoming part

## Assembly of P-100880 at plant PLT03

**Part Number:** P-100880
**Revision:** C.1
**Plant:** PLT03
**Station:** ST-45
**Torque (Nm):** 20
**Cycle time (s):** 160

Step 1: Apply thread locker

Step 2: Visual check

Step 3: Record result

Step 4: Visual check

Step 5: Apply thread locker

Step 6: Fit fasteners

## Assembly of P-100136 at plant PLT02

**Part Number:** P-100136
**Revision:** C.1
**Plant:** PLT02
**Station:** ST-21
**Torque (Nm):** 5

**Cycle time (s):** 267

Step 1: Fit fasteners

Step 2: Inspect incoming part

Step 3: Clean mating surface

Step 4: Move to next station

Step 5: Record result