WORK INSTRUCTION

Document ID: DOC-0002197
Project: PRJ-037
Uploaded on: 2025-09-17
Uploaded by: user162
Export class: EAR99

Assembly of P-101809 at plant PLT04

Part Number: P-101809
Revision: A.1
Plant: PLT04
Station: ST-97
Torque (Nm): 2.5
Cycle time (s): 44

Step 1: Visual check

Step 2: Visual check

Step 3: Torque to specification

Step 4: Apply thread locker

Step 5: Fit fasteners

Step 6: Inspect incoming part

Step 7: Inspect incoming part

Assembly of P-103325 at plant PLT03

Part Number: P-103325
Revision: A.1
Plant: PLT03
Station: ST-22
Torque (Nm): 8
Cycle time (s): 35

Step 1: Clean mating surface

Step 2: Clean mating surface

Step 3: Inspect incoming part

Step 4: Apply thread locker

Step 5: Torque to specification

Step 6: Clean mating surface

Step 7: Clean mating surface

Step 8: Move to next station