WORK INSTRUCTION

Document ID: DOC-0002940
Project: PRJ-039
Uploaded on: 2026-09-02
Uploaded by: user024
Export class: EAR99

Assembly of P-102496 at plant PLT03

Part Number: P-102496
Revision: A.1
Plant: PLT03
Station: ST-48
Torque (Nm): 12
Cycle time (s): 234

Step 1: Visual check

Step 2: Visual check

Step 3: Torque to specification

Step 4: Inspect incoming part

Step 5: Inspect incoming part

Assembly of P-101045 at plant PLT04

Part Number: P-101045
Revision: C.1
Plant: PLT04
Station: ST-86
Torque (Nm): 12
Cycle time (s): 98

Step 1: Record result

Step 2: Clean mating surface

Step 3: Apply thread locker

Step 4: Clean mating surface

Step 5: Clean mating surface