WORK INSTRUCTION

Document ID: DOC-0000035
Project: PRJ-025
Uploaded on: 2022-11-21
Uploaded by: user071
Export class: EAR99

Assembly of P-100064 at plant PLT04

Part Number: P-100064
Revision: A.1
Plant: PLT04
Station: ST-90
Torque (Nm): 20
Cycle time (s): 83

Step 1: Visual check

Step 2: Record result

Step 3: Clean mating surface

Step 4: Clean mating surface

Step 5: Visual check

Step 6: Clean mating surface

Assembly of P-100049 at plant PLT04

Part Number: P-100049
Revision: A.1
Plant: PLT04
Station: ST-81
Torque (Nm): 12
Cycle time (s): 148

Step 1: Clean mating surface

Step 2: Clean mating surface

Step 3: Fit fasteners

Step 4: Record result

Step 5: Move to next station

Step 6: Inspect incoming part

Step 7: Apply thread locker

Assembly of P-100047 at plant PLT04

Part Number: P-100047
Revision: A.1
Plant: PLT04
Station: ST-44
Torque (Nm): 8
Cycle time (s): 39

Step 1: Torque to specification

Step 2: Inspect incoming part

Step 3: Move to next station

Step 4: Visual check

Step 5: Move to next station