WORK INSTRUCTION

Document ID: DOC-0000055
Project: PRJ-007
Uploaded on: 2022-11-26
Uploaded by: user153
Export class: EAR99

Assembly of P-100014 at plant PLT01

Part Number: P-100014
Revision: A.1
Plant: PLT01
Station: ST-24
Torque (Nm): 5
Cycle time (s): 206

Step 1: Inspect incoming part

Step 2: Apply thread locker

Step 3: Visual check

Step 4: Move to next station

Step 5: Torque to specification

Step 6: Inspect incoming part

Step 7: Record result

Step 8: Clean mating surface

Assembly of P-100033 at plant PLT01

Part Number: P-100033
Revision: A.1
Plant: PLT01
Station: ST-31
Torque (Nm): 12
Cycle time (s): 265

Step 1: Move to next station

Step 2: Apply thread locker

Step 3: Record result

Step 4: Fit fasteners

Step 5: Clean mating surface

Step 6: Move to next station

Step 7: Visual check

Assembly of P-100076 at plant PLT01

Part Number: P-100076
Revision: A.1
Plant: PLT01
Station: ST-26

Torque (Nm):	20
Cycle time (s):	81

Step 1: Visual check

Step 2: Inspect incoming part

Step 3: Torque to specification

Step 4: Torque to specification

Step 5: Inspect incoming part