WORK INSTRUCTION

Document ID: DOC-0000071
Project: PRJ-006
Uploaded on: 2022-12-06
Uploaded by: user028
Export class: EAR99

Assembly of P-100104 at plant PLT03

Part Number: P-100104
Revision: A.1
Plant: PLT03
Station: ST-46
Torque (Nm): 5
Cycle time (s): 70

Step 1: Fit fasteners

Step 2: Inspect incoming part

Step 3: Fit fasteners

Step 4: Move to next station

Step 5: Record result

Step 6: Clean mating surface

Step 7: Visual check

Assembly of P-100121 at plant PLT02

Part Number: P-100121
Revision: A.1
Plant: PLT02
Station: ST-45
Torque (Nm): 8
Cycle time (s): 98

Step 1: Fit fasteners

Step 2: Inspect incoming part

Step 3: Torque to specification

Step 4: Visual check

Step 5: Torque to specification