ITAR CONTROLLED - USML CATEGORY XIX

# WORK INSTRUCTION

**Document ID:** DOC-0000087
**Project:** PRJ-030
**Uploaded on:** 2022-12-18
**Uploaded by:** user145
**Export class:** ITAR-USML-XIX

## Assembly of P-100115 at plant PLT02

**Part Number:** P-100115
**Revision:** A.1
**Plant:** PLT02
**Station:** ST-47
**Torque (Nm):** 5
**Cycle time (s):** 178

Step 1: Apply thread locker

Step 2: Clean mating surface

Step 3: Move to next station

Step 4: Torque to specification

Step 5: Clean mating surface

Step 6: Move to next station

## Assembly of P-100070 at plant PLT04

**Part Number:** P-100070
**Revision:** A.1
**Plant:** PLT04
**Station:** ST-71
**Torque (Nm):** 12
**Cycle time (s):** 48

Step 1: Torque to specification

Step 2: Inspect incoming part

Step 3: Fit fasteners

Step 4: Apply thread locker

Step 5: Apply thread locker

Step 6: Fit fasteners

Step 7: Record result