WORK INSTRUCTION

Document ID: DOC-0000092
Project: PRJ-035
Uploaded on: 2022-12-19
Uploaded by: user097
Export class: EAR99

Assembly of P-100085 at plant PLT02

Part Number: P-100085
Revision: A.1
Plant: PLT02
Station: ST-36
Torque (Nm): 20
Cycle time (s): 210

Step 1: Move to next station

Step 2: Torque to specification

Step 3: Move to next station

Step 4: Record result

Step 5: Visual check

Step 6: Visual check

Step 7: Visual check

Step 8: Clean mating surface

Assembly of P-100162 at plant PLT02

Part Number: P-100162
Revision: A.1
Plant: PLT02
Station: ST-17
Torque (Nm): 2.5
Cycle time (s): 198

Step 1: Torque to specification

Step 2: Clean mating surface

Step 3: Record result

Step 4: Inspect incoming part

Step 5: Clean mating surface

Step 6: Visual check

Step 7: Apply thread locker

Step 8: Torque to specification