ITAR CONTROLLED - USML CATEGORY XIX

WORK INSTRUCTION

Document ID: DOC-0000131
Project: PRJ-004
Uploaded on: 2023-01-06
Uploaded by: user040
Export class: ITAR-USML-XIX

Assembly of P-100064 at plant PLT04

Part Number: P-100064
Revision: A.1
Plant: PLT04
Station: ST-27
Torque (Nm): 5
Cycle time (s): 45

Step 1: Clean mating surface

Step 2: Fit fasteners

Step 3: Inspect incoming part

Step 4: Visual check

Step 5: Record result

Step 6: Inspect incoming part

Step 7: Fit fasteners

Step 8: Apply thread locker

Assembly of P-100191 at plant PLT04

Part Number: P-100191
Revision: A.1
Plant: PLT04
Station: ST-89
Torque (Nm): 20
Cycle time (s): 129

Step 1: Fit fasteners

Step 2: Fit fasteners

Step 3: Clean mating surface

Step 4: Record result

Step 5: Move to next station

Assembly of P-100216 at plant PLT03

Part Number: P-100216
Revision: A.1
Plant: PLT03
Station: ST-43

Torque (Nm):	5
Cycle time (s):	191

Step 1: Apply thread locker

Step 2: Apply thread locker

Step 3: Record result

Step 4: Torque to specification

Step 5: Inspect incoming part