WORK INSTRUCTION

Document ID: DOC-0000204
Project: PRJ-002
Uploaded on: 2023-02-11
Uploaded by: user154
Export class: EAR99

Assembly of P-100058 at plant PLT01

Part Number: P-100058
Revision: A.1
Plant: PLT01
Station: ST-19
Torque (Nm): 12
Cycle time (s): 221

Step 1: Record result

Step 2: Clean mating surface

Step 3: Apply thread locker

Step 4: Torque to specification

Step 5: Inspect incoming part

Step 6: Record result

Assembly of P-100147 at plant PLT04

Part Number: P-100147
Revision: A.1
Plant: PLT04
Station: ST-42
Torque (Nm): 2.5
Cycle time (s): 130

Step 1: Visual check

Step 2: Record result

Step 3: Move to next station

Step 4: Record result

Step 5: Inspect incoming part

Step 6: Clean mating surface