WORK INSTRUCTION

Document ID: DOC-0000247
Project: PRJ-031
Uploaded on: 2023-02-28
Uploaded by: user057
Export class: EAR99

Assembly of P-100106 at plant PLT04

Part Number: P-100106
Revision: B.1
Plant: PLT04
Station: ST-97
Torque (Nm): 5
Cycle time (s): 223

Step 1: Move to next station

Step 2: Move to next station

Step 3: Record result

Step 4: Record result

Step 5: Inspect incoming part

Step 6: Apply thread locker

Step 7: Torque to specification

Step 8: Inspect incoming part

Assembly of P-100052 at plant PLT03

Part Number: P-100052
Revision: A.1
Plant: PLT03
Station: ST-27
Torque (Nm): 20
Cycle time (s): 42

Step 1: Torque to specification

Step 2: Move to next station

Step 3: Fit fasteners

Step 4: Move to next station

Step 5: Visual check

Step 6: Fit fasteners

Step 7: Move to next station

Step 8: Visual check

Assembly of P-100361 at plant PLT04

Part Number: P-100361
Revision: A.1
Plant: PLT04

Station:	ST-47
Torque (Nm):	5
Cycle time (s):	65

Step 1: Move to next station

Step 2: Record result

Step 3: Record result

Step 4: Move to next station

Step 5: Inspect incoming part

Step 6: Clean mating surface

Step 7: Torque to specification

Step 8: Fit fasteners