# WORK INSTRUCTION

**Document ID:** DOC-0000444
**Project:** PRJ-033
**Uploaded on:** 2023-06-01
**Uploaded by:** user017
**Export class:** EAR99

## Assembly of P-100244 at plant PLT03

**Part Number:** P-100244
**Revision:** B.1
**Plant:** PLT03
**Station:** ST-10
**Torque (Nm):** 5
**Cycle time (s):** 285

Step 1: Move to next station

Step 2: Visual check

Step 3: Inspect incoming part

Step 4: Apply thread locker

Step 5: Torque to specification

Step 6: Torque to specification

Step 7: Record result

Step 8: Inspect incoming part

## Assembly of P-100231 at plant PLT03

**Part Number:** P-100231
**Revision:** A.1
**Plant:** PLT03
**Station:** ST-70
**Torque (Nm):** 5
**Cycle time (s):** 158

Step 1: Visual check

Step 2: Clean mating surface

Step 3: Torque to specification

Step 4: Move to next station

Step 5: Visual check

Step 6: Apply thread locker

Step 7: Apply thread locker