**EXPORT CONTROLLED - ECCN 3A001**

# WORK INSTRUCTION

**Document ID:** DOC-0000454
**Project:** PRJ-016
**Uploaded on:** 2023-06-06
**Uploaded by:** user188
**Export class:** ECCN-3A001

## Assembly of P-100026 at plant PLT01

**Part Number:** P-100026
**Revision:** A.1
**Plant:** PLT01
**Station:** ST-47
**Torque (Nm):** 2.5
**Cycle time (s):** 265

Step 1: Record result

Step 2: Clean mating surface

Step 3: Visual check

Step 4: Inspect incoming part

Step 5: Inspect incoming part

## Assembly of P-100434 at plant PLT02

**Part Number:** P-100434
**Revision:** A.1
**Plant:** PLT02
**Station:** ST-95
**Torque (Nm):** 20
**Cycle time (s):** 124

Step 1: Clean mating surface

Step 2: Apply thread locker

Step 3: Move to next station

Step 4: Clean mating surface

Step 5: Record result

Step 6: Record result

Step 7: Record result

Step 8: Torque to specification