WORK INSTRUCTION

Document ID: DOC-0000665
Project: PRJ-012
Uploaded on: 2023-09-08
Uploaded by: user011
Export class: EAR99

Assembly of P-100854 at plant PLT03

Part Number: P-100854
Revision: A.1
Plant: PLT03
Station: ST-36
Torque (Nm): 20
Cycle time (s): 104

Step 1: Torque to specification

Step 2: Visual check

Step 3: Clean mating surface

Step 4: Clean mating surface

Step 5: Record result

Step 6: Move to next station

Step 7: Clean mating surface

Assembly of P-100710 at plant PLT03

Part Number: P-100710
Revision: A.1
Plant: PLT03
Station: ST-59
Torque (Nm): 5
Cycle time (s): 247

Step 1: Visual check

Step 2: Apply thread locker

Step 3: Clean mating surface

Step 4: Visual check

Step 5: Move to next station

Step 6: Inspect incoming part

Step 7: Move to next station

Assembly of P-100590 at plant PLT04

Part Number: P-100590
Revision: A.1
Plant: PLT04
Station: ST-43
Torque (Nm): 2.5

Cycle time (s): 159

Step 1: Clean mating surface

Step 2: Torque to specification

Step 3: Move to next station

Step 4: Move to next station

Step 5: Fit fasteners