WORK INSTRUCTION

Document ID: DOC-0000946
Project: PRJ-012
Uploaded on: 2024-02-11
Uploaded by: user105
Export class: EAR99

Assembly of P-100712 at plant PLT04

Part Number: P-100712
Revision: A.1
Plant: PLT04
Station: ST-86
Torque (Nm): 20
Cycle time (s): 34

Step 1: Visual check

Step 2: Visual check

Step 3: Visual check

Step 4: Visual check

Step 5: Fit fasteners

Step 6: Clean mating surface

Step 7: Clean mating surface

Assembly of P-100904 at plant PLT04

Part Number: P-100904
Revision: A.1
Plant: PLT04
Station: ST-32
Torque (Nm): 12
Cycle time (s): 46

Step 1: Record result

Step 2: Fit fasteners

Step 3: Visual check

Step 4: Fit fasteners

Step 5: Record result

Step 6: Inspect incoming part

Step 7: Inspect incoming part