WORK INSTRUCTION

Document ID: DOC-0001182
Project: PRJ-025
Uploaded on: 2024-06-03
Uploaded by: user075
Export class: EAR99

Assembly of P-101220 at plant PLT02

Part Number: P-101220
Revision: A.1
Plant: PLT02
Station: ST-90
Torque (Nm): 12
Cycle time (s): 194

Step 1: Inspect incoming part

Step 2: Clean mating surface

Step 3: Clean mating surface

Step 4: Torque to specification

Step 5: Inspect incoming part

Assembly of P-100926 at plant PLT01

Part Number: P-100926
Revision: A.1
Plant: PLT01
Station: ST-75
Torque (Nm): 20
Cycle time (s): 299

Step 1: Torque to specification

Step 2: Move to next station

Step 3: Clean mating surface

Step 4: Move to next station

Step 5: Inspect incoming part

Step 6: Record result

Step 7: Record result

Step 8: Torque to specification

Assembly of P-101057 at plant PLT04

Part Number: P-101057
Revision: A.1
Plant: PLT04
Station: ST-13
Torque (Nm): 12
Cycle time (s): 222

Step 1: Clean mating surface

Step 2: Record result

Step 3: Apply thread locker

Step 4: Visual check

Step 5: Clean mating surface