WORK INSTRUCTION

Document ID: DOC-0001218
Project: PRJ-033
Uploaded on: 2024-06-19
Uploaded by: user126
Export class: EAR99

Assembly of P-101094 at plant PLT02

Part Number: P-101094
Revision: A.1
Plant: PLT02
Station: ST-41
Torque (Nm): 8
Cycle time (s): 121

Step 1: Torque to specification

Step 2: Inspect incoming part

Step 3: Inspect incoming part

Step 4: Move to next station

Step 5: Record result

Assembly of P-101129 at plant PLT01

Part Number: P-101129
Revision: A.1
Plant: PLT01
Station: ST-55
Torque (Nm): 8
Cycle time (s): 117

Step 1: Fit fasteners

Step 2: Clean mating surface

Step 3: Visual check

Step 4: Move to next station

Step 5: Inspect incoming part