# WORK INSTRUCTION

**Document ID:** DOC-0001363
**Project:** PRJ-029
**Uploaded on:** 2024-08-20
**Uploaded by:** user193
**Export class:** EAR99

## Assembly of P-101798 at plant PLT02

**Part Number:** P-101798
**Revision:** B.1
**Plant:** PLT02
**Station:** ST-83
**Torque (Nm):** 5
**Cycle time (s):** 185

Step 1: Torque to specification

Step 2: Inspect incoming part

Step 3: Move to next station

Step 4: Clean mating surface

Step 5: Apply thread locker

Step 6: Apply thread locker

Step 7: Clean mating surface

## Assembly of P-102146 at plant PLT03

**Part Number:** P-102146
**Revision:** A.1
**Plant:** PLT03
**Station:** ST-34
**Torque (Nm):** 20
**Cycle time (s):** 252

Step 1: Visual check

Step 2: Clean mating surface

Step 3: Torque to specification

Step 4: Apply thread locker

Step 5: Visual check

Step 6: Inspect incoming part