WORK INSTRUCTION

Document ID: DOC-0001481
Project: PRJ-003
Uploaded on: 2024-10-12
Uploaded by: user037
Export class: EAR99

Assembly of P-101847 at plant PLT01

Part Number: P-101847
Revision: A.1
Plant: PLT01
Station: ST-82
Torque (Nm): 5
Cycle time (s): 81

Step 1: Clean mating surface

Step 2: Record result

Step 3: Apply thread locker

Step 4: Visual check

Step 5: Inspect incoming part

Step 6: Clean mating surface

Step 7: Inspect incoming part

Step 8: Inspect incoming part

Assembly of P-102005 at plant PLT04

Part Number: P-102005
Revision: A.1
Plant: PLT04
Station: ST-30
Torque (Nm): 2.5
Cycle time (s): 150

Step 1: Record result

Step 2: Move to next station

Step 3: Inspect incoming part

Step 4: Torque to specification

Step 5: Clean mating surface