WORK INSTRUCTION

Document ID: DOC-0001509
Project: PRJ-001
Uploaded on: 2024-10-22
Uploaded by: user071
Export class: EAR99

Assembly of P-101452 at plant PLT04

Part Number: P-101452
Revision: A.1
Plant: PLT04
Station: ST-97
Torque (Nm): 12
Cycle time (s): 294

Step 1: Clean mating surface

Step 2: Inspect incoming part

Step 3: Record result

Step 4: Clean mating surface

Step 5: Fit fasteners

Assembly of P-100526 at plant PLT04

Part Number: P-100526
Revision: A.1
Plant: PLT04
Station: ST-53
Torque (Nm): 2.5
Cycle time (s): 203

Step 1: Fit fasteners

Step 2: Visual check

Step 3: Fit fasteners

Step 4: Torque to specification

Step 5: Fit fasteners

Step 6: Clean mating surface