WORK INSTRUCTION

Document ID: DOC-0001610
Project: PRJ-012
Uploaded on: 2024-12-08
Uploaded by: user001
Export class: EAR99

Assembly of P-100583 at plant PLT04

Part Number: P-100583
Revision: B.1
Plant: PLT04
Station: ST-24
Torque (Nm): 20
Cycle time (s): 157

Step 1: Visual check

Step 2: Move to next station

Step 3: Inspect incoming part

Step 4: Clean mating surface

Step 5: Fit fasteners

Step 6: Visual check

Assembly of P-101417 at plant PLT04

Part Number: P-101417
Revision: B.1
Plant: PLT04
Station: ST-20
Torque (Nm): 8
Cycle time (s): 223

Step 1: Clean mating surface

Step 2: Torque to specification

Step 3: Torque to specification

Step 4: Apply thread locker

Step 5: Torque to specification

Assembly of P-102033 at plant PLT04

Part Number: P-102033
Revision: A.1
Plant: PLT04
Station: ST-48
Torque (Nm): 8
Cycle time (s): 102

Step 1: Apply thread locker

Step 2: Clean mating surface

Step 3: Torque to specification

Step 4: Fit fasteners

Step 5: Inspect incoming part