WORK INSTRUCTION

Document ID: DOC-0001931
Project: PRJ-020
Uploaded on: 2025-05-14
Uploaded by: user104
Export class: EAR99

Assembly of P-100006 at plant PLT04

Part Number: P-100006
Revision: C.1
Plant: PLT04
Station: ST-92
Torque (Nm): 2.5
Cycle time (s): 76

Step 1: Move to next station

Step 2: Inspect incoming part

Step 3: Clean mating surface

Step 4: Inspect incoming part

Step 5: Record result

Assembly of P-101479 at plant PLT04

Part Number: P-101479
Revision: A.1
Plant: PLT04
Station: ST-97
Torque (Nm): 12
Cycle time (s): 163

Step 1: Torque to specification

Step 2: Apply thread locker

Step 3: Inspect incoming part

Step 4: Inspect incoming part

Step 5: Clean mating surface

Assembly of P-102702 at plant PLT01

Part Number: P-102702
Revision: A.1
Plant: PLT01
Station: ST-30
Torque (Nm): 2.5
Cycle time (s): 33

Step 1: Move to next station

Step 2: Record result

Step 3: Inspect incoming part

Step 4: Record result

Step 5: Torque to specification

Step 6: Torque to specification