WORK INSTRUCTION

Document ID: DOC-0001978
Project: PRJ-008
Uploaded on: 2025-06-03
Uploaded by: user116
Export class: EAR99

Assembly of P-102061 at plant PLT04

Part Number: P-102061
Revision: A.1
Plant: PLT04
Station: ST-77
Torque (Nm): 12
Cycle time (s): 279

Step 1: Torque to specification

Step 2: Visual check

Step 3: Inspect incoming part

Step 4: Visual check

Step 5: Record result

Step 6: Clean mating surface

Step 7: Move to next station

Step 8: Inspect incoming part

Assembly of P-102395 at plant PLT02

Part Number: P-102395
Revision: A.1
Plant: PLT02
Station: ST-22
Torque (Nm): 12
Cycle time (s): 33

Step 1: Record result

Step 2: Fit fasteners

Step 3: Clean mating surface

Step 4: Fit fasteners

Step 5: Clean mating surface

Step 6: Apply thread locker

Step 7: Torque to specification

Assembly of P-100340 at plant PLT01

Part Number: P-100340
Revision: B.1
Plant: PLT01
Station: ST-65

Torque (Nm):	2.5
Cycle time (s):	255

Step 1: Move to next station

Step 2: Visual check

Step 3: Inspect incoming part

Step 4: Fit fasteners

Step 5: Inspect incoming part

Step 6: Clean mating surface

Step 7: Move to next station

Step 8: Record result