WORK INSTRUCTION

Document ID: DOC-0002007
Project: PRJ-034
Uploaded on: 2025-06-17
Uploaded by: user154
Export class: EAR99

Assembly of P-100408 at plant PLT04

Part Number: P-100408
Revision: B.1
Plant: PLT04
Station: ST-53
Torque (Nm): 2.5
Cycle time (s): 131

Step 1: Inspect incoming part

Step 2: Inspect incoming part

Step 3: Visual check

Step 4: Fit fasteners

Step 5: Apply thread locker

Step 6: Clean mating surface

Assembly of P-102063 at plant PLT01

Part Number: P-102063
Revision: A.1
Plant: PLT01
Station: ST-47
Torque (Nm): 5
Cycle time (s): 292

Step 1: Apply thread locker

Step 2: Record result

Step 3: Visual check

Step 4: Visual check

Step 5: Record result

Step 6: Inspect incoming part

Step 7: Torque to specification

Assembly of P-102950 at plant PLT03

Part Number: P-102950
Revision: A.1
Plant: PLT03
Station: ST-89
Torque (Nm): 2.5
Cycle time (s): 297

Step 1: Clean mating surface

Step 2: Inspect incoming part

Step 3: Move to next station

Step 4: Torque to specification

Step 5: Inspect incoming part

Step 6: Record result

Step 7: Fit fasteners

Step 8: Inspect incoming part