WORK INSTRUCTION

Document ID: DOC-0002273
Project: PRJ-020
Uploaded on: 2025-10-22
Uploaded by: user011
Export class: EAR99

Assembly of P-102677 at plant PLT04

Part Number: P-102677
Revision: A.1
Plant: PLT04
Station: ST-63
Torque (Nm): 5
Cycle time (s): 269

Step 1: Clean mating surface

Step 2: Torque to specification

Step 3: Record result

Step 4: Torque to specification

Step 5: Move to next station

Step 6: Fit fasteners

Step 7: Fit fasteners

Step 8: Visual check

Assembly of P-100257 at plant PLT02

Part Number: P-100257
Revision: D.1
Plant: PLT02
Station: ST-31
Torque (Nm): 2.5
Cycle time (s): 229

Step 1: Torque to specification

Step 2: Apply thread locker

Step 3: Clean mating surface

Step 4: Record result

Step 5: Record result

Step 6: Inspect incoming part

Step 7: Apply thread locker

Assembly of P-100612 at plant PLT02

Part Number: P-100612
Revision: B.1
Plant: PLT02
Station: ST-26

Torque (Nm):	12
Cycle time (s):	296

Step 1: Visual check

Step 2: Torque to specification

Step 3: Clean mating surface

Step 4: Record result

Step 5: Move to next station

Step 6: Move to next station

Step 7: Visual check