WORK INSTRUCTION

Document ID: DOC-0002554
Project: PRJ-035
Uploaded on: 2026-03-01
Uploaded by: user135
Export class: EAR99

Assembly of P-103843 at plant PLT03

Part Number: P-103843
Revision: A.1
Plant: PLT03
Station: ST-79
Torque (Nm): 20
Cycle time (s): 300

Step 1: Visual check

Step 2: Move to next station

Step 3: Apply thread locker

Step 4: Inspect incoming part

Step 5: Clean mating surface

Step 6: Torque to specification

Step 7: Clean mating surface

Assembly of P-103107 at plant PLT01

Part Number: P-103107
Revision: A.1
Plant: PLT01
Station: ST-12
Torque (Nm): 5
Cycle time (s): 70

Step 1: Move to next station

Step 2: Clean mating surface

Step 3: Visual check

Step 4: Move to next station

Step 5: Visual check

Step 6: Move to next station

Step 7: Torque to specification

Assembly of P-103312 at plant PLT03

Part Number: P-103312
Revision: A.1
Plant: PLT03
Station: ST-66
Torque (Nm): 5

Cycle time (s): 37

Step 1: Visual check

Step 2: Apply thread locker

Step 3: Inspect incoming part

Step 4: Torque to specification

Step 5: Apply thread locker

Step 6: Inspect incoming part

Step 7: Visual check