WORK INSTRUCTION

Document ID: DOC-0002594
Project: PRJ-013
Uploaded on: 2026-03-16
Uploaded by: user143
Export class: EAR99

Assembly of P-103938 at plant PLT02

Part Number: P-103938
Revision: A.1
Plant: PLT02
Station: ST-16
Torque (Nm): 8
Cycle time (s): 139

Step 1: Visual check

Step 2: Fit fasteners

Step 3: Inspect incoming part

Step 4: Record result

Step 5: Record result

Step 6: Visual check

Step 7: Record result

Assembly of P-100977 at plant PLT02

Part Number: P-100977
Revision: A.1
Plant: PLT02
Station: ST-15
Torque (Nm): 5
Cycle time (s): 210

Step 1: Apply thread locker

Step 2: Inspect incoming part

Step 3: Move to next station

Step 4: Torque to specification

Step 5: Torque to specification

Step 6: Inspect incoming part

Assembly of P-103128 at plant PLT03

Part Number: P-103128
Revision: A.1
Plant: PLT03
Station: ST-90
Torque (Nm): 2.5
Cycle time (s): 272

Step 1: Record result

Step 2: Apply thread locker

Step 3: Clean mating surface

Step 4: Torque to specification

Step 5: Move to next station

Step 6: Clean mating surface

Step 7: Clean mating surface