WORK INSTRUCTION

Document ID: DOC-0002692
Project: PRJ-030
Uploaded on: 2026-05-04
Uploaded by: user139
Export class: EAR99

Assembly of P-102618 at plant PLT04

Part Number: P-102618
Revision: B.1
Plant: PLT04
Station: ST-45
Torque (Nm): 5
Cycle time (s): 137

Step 1: Fit fasteners

Step 2: Visual check

Step 3: Visual check

Step 4: Torque to specification

Step 5: Apply thread locker

Step 6: Clean mating surface

Assembly of P-102940 at plant PLT03

Part Number: P-102940
Revision: A.1
Plant: PLT03
Station: ST-40
Torque (Nm): 8
Cycle time (s): 137

Step 1: Torque to specification

Step 2: Visual check

Step 3: Visual check

Step 4: Inspect incoming part

Step 5: Visual check

Step 6: Torque to specification

Step 7: Clean mating surface

Assembly of P-101043 at plant PLT02

Part Number: P-101043
Revision: A.1
Plant: PLT02
Station: ST-65
Torque (Nm): 20
Cycle time (s): 58

Step 1: Clean mating surface

Step 2: Clean mating surface

Step 3: Torque to specification

Step 4: Fit fasteners

Step 5: Record result

Step 6: Clean mating surface

Step 7: Move to next station