EXPORT CONTROLLED - ECCN 3A001

WORK INSTRUCTION

Document ID: DOC-0000454
Project: PRJ-016
Uploaded on: 2023-06-06
Uploaded by: user188
Export class: ECCN-3A001

Assembly of P-100026 at plant PLT01

Part Number: P-100026
Revision: B.1
Plant: PLT01
Station: ST-47
Torque (Nm): 2.5
Cycle time (s): 265

Step 1: Record result

Step 2: Clean mating surface

Step 3: Visual check

Step 4: Inspect incoming part

Step 5: Inspect incoming part

Assembly of P-100441 at plant PLT01

Part Number: P-100441
Revision: A.1
Plant: PLT01
Station: ST-95
Torque (Nm): 20
Cycle time (s): 124

Step 1: Clean mating surface

Step 2: Apply thread locker

Step 3: Move to next station

Step 4: Clean mating surface

Step 5: Record result

Step 6: Record result

Step 7: Record result

Step 8: Torque to specification