WORK INSTRUCTION

Document ID: DOC-0001486
Project: PRJ-015
Uploaded on: 2024-10-13
Uploaded by: user106
Export class: EAR99

Assembly of P-101846 at plant PLT04

Part Number: P-101846
Revision: A.1
Plant: PLT04
Station: ST-41
Torque (Nm): 2.5
Cycle time (s): 96

Step 1: Move to next station

Step 2: Torque to specification

Step 3: Record result

Step 4: Move to next station

Step 5: Clean mating surface

Assembly of P-101738 at plant PLT02

Part Number: P-101738
Revision: A.1
Plant: PLT02
Station: ST-86
Torque (Nm): 20
Cycle time (s): 150

Step 1: Apply thread locker

Step 2: Record result

Step 3: Clean mating surface

Step 4: Fit fasteners

Step 5: Inspect incoming part

Step 6: Clean mating surface

Step 7: Clean mating surface

Assembly of P-100025 at plant PLT02

Part Number: P-100025
Revision: A.1
Plant: PLT02
Station: ST-30
Torque (Nm): 12
Cycle time (s): 99

Step 1: Apply thread locker

Step 2: Move to next station

Step 3: Record result

Step 4: Visual check

Step 5: Move to next station

Step 6: Visual check

Step 7: Move to next station