WORK INSTRUCTION

Document ID: DOC-0000674
Project: PRJ-003
Uploaded on: 2023-09-17
Uploaded by: user094
Export class: EAR99

Assembly of P-100209 at plant PLT04

Part Number: P-100209
Revision: A.1
Plant: PLT04
Station: ST-76
Torque (Nm): 20
Cycle time (s): 54

Step 1: Torque to specification

Step 2: Move to next station

Step 3: Apply thread locker

Step 4: Clean mating surface

Step 5: Apply thread locker

Step 6: Clean mating surface

Step 7: Record result

Step 8: Visual check

Assembly of P-100929 at plant PLT02

Part Number: P-100929
Revision: A.1
Plant: PLT02
Station: ST-79
Torque (Nm): 8
Cycle time (s): 288

Step 1: Apply thread locker

Step 2: Visual check

Step 3: Clean mating surface

Step 4: Inspect incoming part

Step 5: Visual check

Step 6: Move to next station

Assembly of P-100874 at plant PLT04

Part Number: P-100874
Revision: A.1
Plant: PLT04
Station: ST-59
Torque (Nm): 2.5

Cycle time (s): 163

Step 1: Inspect incoming part

Step 2: Torque to specification

Step 3: Torque to specification

Step 4: Move to next station

Step 5: Clean mating surface

Step 6: Inspect incoming part